


**PRODUCT: 1/4" RICE**  
**PLANT(S): LINCOLN, ROOSEVELT, SHREWSBURY**

### PARTICLE SIZE DISTRIBUTION

<u>Sieve Size</u>	<u>Avg. % Passing</u>	<u>PA Spec</u>
#200	1.9	0-3
#100	3	0-6
#50	4	
#30	5	
#16	6	
#8	16	0-45
#4	64	35-80
3/8"	100	100



We herewith certify that our material is crushed limestone, and is produced at our plant(s) specified above. The results reported above are from "typical sieve analysis reports". Please be aware that results may vary, as they are dependent upon mineral deposit variations. Please call for updated test analysis.